


EVANA TECHNOLOGIES

Crack treatment on stainless steel of power plant turbine

- Stainless steel ablation
- Task: ablated area: (3x3)mm, depth: >20μm
- Result: corner and bottom surface structure



No.	No.1	No.2	No.3
Machining time	15min	50min	50min
Depth	20μm	45μm	35μm

